

Broil King®



BARON 420

9229-52

9229-53

9229-56



BARON 440

9229-62

9229-63

9229-66



BARON 420S

9225-52

9225-53

9225-56



BARON 440S

9225-62

9225-63

9225-66

Onward
MANUFACTURING COMPANY

SINCE 1906











1000 EAST MARKET STREET
HUNTINGTON, INDIANA, 46750, USA

50084-S45EU Rev F 10/15



HARDWARE INCLUDED / MATERIAL INCLUS / EQUIPOS INCLUIDO




Y-12865		X30	S21125		X8
Y-11565		X4			
Y-29310		X4	Y-12310		X4
S21235		X2	Y-12857		X4
			S21233		X2
Y-11793		X4	Y-12127		X2
S35094		X1	Y-29304		X2




TOOLS REQUIRED / OUTILS NECESSAIRES / HERRAMIENTAS NECESARIAS




#3 PHILLIPS




#2 PHILLIPS




7/16"





1

(8) 




2

(4)  (4) 





3




4

(8)



5


(4) 



6



(4) 

(1) 




7

(4)




8



9



(2)

A





(2)

B




10



(4)





11





12



13




14




15

(4)




16





17






(4)





18


(1)







20

(2)  (2) 


(1) 




21





22





23








1



2



3

